

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

AH178  
NE  
1/4-1/2  
0.315 mi.  
1663 ft.

UNDER BELT PARKWAY  
SHELL RD/BELT PARKWAY  
BROOKLYN, NY

NY Spills S102240530  
N/A

Site 2 of 2 in cluster AH

Relative:  
Higher

Actual:  
17 ft.

SPILLS:

Name: UNDER BELT PARKWAY  
Address: SHELL RD/BELT PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9605295 / 1996-07-24  
Facility ID: 9605295  
Facility Type: ER  
DER Facility ID: 208829  
Site ID: 254938  
DEC Region: 2  
Spill Cause: Abandoned Drums  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1996-07-24  
Investigator: SMMARTIN  
Referred To: Not reported  
Reported to Dept: 1996-07-24  
CID: 199  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1996-07-24  
  
Spill Record Last Update: 1996-09-05  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: MR PISCIOPTA  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was MARTINKAT "  
  
Remarks: "caller reports that the notifier from brooklyn gas found 6 barrels of material abandoned at location - unk size of barrels- unk what the material is inside them"

All Materials:

Site ID: 254938  
Operable Unit ID: 1036178  
Operable Unit: 01  
Material ID: 348044  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported